Building Safety Report

NAME OF SCHOOL: ST-XAUGER'S. School, Member
(District-MANSA)
As per report of Assistant/Junior Engineer on his visually inspection, the above mentioned school seems visually safe subject to the following observations and conditions.
The Parameters to check the stability and safety of building such as structural Design.
Architectural Drawings, Bearing capacity, Foundation details, Structural drawings,
Technical Specifications, Test reports of Material used and Quality control reports are not
available
2 In case any addition, alteration, expansion and modification to this building are required/to
be done, regarding this, inspection of undersigned may be arranged and obtained a
certification:after the completion from the undersigned.
In the case of building is affected by flood or if there is any settlement of walls foundation
of roof etc. immediately inspection of the undersigned arranged to check the stallings, and
safety of the building.
4. A separate certificate regarding Fire Fighting should be obtained from the competent
Authority,
5. A separate certificate regarding Electrical works should be obtained from the competent.
Authority.
6 The owner of the building/Management is fully responsible regarding safety of the building
the state of this report
7. This report is for the covered area of the school building 51346-12 or which is
submitted by the owner of the school building as per drawing.
8. The building of the school is constructed as framed structure/brick masonry.
9. This report is not valid for legal purpose.
10. That the fee charges for the year 2022-23 definitions
MY TIST VICINITIES THAT OF TERMINATION OF THE PROPERTY OF THE
above building may be used for normal use for One year, up to 31-3-2023 Subject to the
above conditions.
(w) 1 will
Assistant United Francis of the Control of the Cont
Assistant/Junior Engineer Sub Divisional Engineer Phys. Sub Divis. No. 7 PAID (B&R)
PRINCIPAL St. Xavier's School
Mansa Khurd

Distt. Mansa Punjab-151505